



The Original True Cone 10 Kiln


Traditional Downdraft Vent Installation

Pros:

- This method makes a negative pressure in the kiln and moves the right amount of air to effectively vent fumes from the kiln.

Cons:

- Holes in the kiln lid can draw dust into the kiln, potentially impacting glazed ware on the top shelf.
- Holes in the floor can become clogged with debris over time and affect the efficiency of the motor.



Cone Art Recommended Downdraft Vent Installation

Pros:

- This method moves the exact same amount of air as above, effectively venting fumes from the kiln.
- No lid holes means no debris on the top shelf.
- No floor holes means no chance of clogged exit holes, helping keep the motor healthy long term.

